## **Western Forest Products**

DEFINING A HIGHER STANDARD™



## Environmental Protection Notice Authorization# 111020 Tracking# 409425

Application for a *Permit* under the Provision of the Environmental Management Act.

Western Forest Products Inc., submitted a preliminary permit application to the Director to authorize the discharge of effluent. The source of discharge of effluent is produced by the Ladysmith Sawmill. This permit will ensure that Western is alignment with all Environmental Management Act and subsequent permitting requirements.

Regulated under B.C.'s *Environmental Management Act*, sawmill "effluent" consists of rainwater that contacts fine woody material and so contains natural wood extractives, such as resin acids and tannins/lignins. Rainwater that contacts galvanized material, like roofing, may contain zinc and other metals. Effluent discharge is highly variable depending on rainfall events.

The Ladysmith Sawmill is located at the foot of Ludlow Road, Ladysmith, BC, within the *Cowichan Valley Regional District* (see Figure 1).

The maximum rate of *effluent discharge from this facility* will be determined through the permitting process to meet the *Environmental Management Act* requirements. *The* operating period for this facility is *16 hours/day*, *5 days/week*. The characteristics of the *effluent discharge* reflects what would be typical at a sawmill including wood extractives, hydrocarbons, and metals.

Any person who may be adversely affected by the proposed *effluent* discharge of waste and wishes to provide relevant information may, within 30 days after the last date of posting, publishing, service or display, send written comments to the applicant, with a copy to the Director, Environmental Protection at Authorizations.South@gov.bc.ca. The identity of any respondents and the contents of anything submitted in relation to this application will become part of the public record.

Dated the 10th day of February, 2023

Contact Person: Scott Slee

Email Address: sslee@westernforest.com

Phone: 250-245-2238




Figure 1. Overview of the Ladysmith sawmill. Effluent discharge locations are identified by the red balloons.